

Oil Field Environmental Incident Summary

Incident: 20141208100117 **Date/Time of Notice:** 12/08/2014 10:01

Responsible Party: Black Hills Trucking

Well Operator: OXY USA INC.

Well Name: MILDRED SADOWSKY 2-11-14H-142-97

Field Name: WILLMEN

Well File #: 26538

Date Incident: 12/4/2014 **Time Incident:** 10:30

Facility ID Number:

County: DUNN

Twp: 142

Rng: 97

Sec: 11

Qtr: NE NW

Location Description: Mildred Sodowsky 2 production battery.

Submitted By: Bob Dundas

Received By:

Contact Person: Marlin Hanson
5 GREENWAY PLAZA STE 110
HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	7	Barrels			0	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/21/2016

Clean Up Concluded: 12/5/2014

Risk Evaluation:

No immediate risks have been identified.

Areal Extent:

Spill was fully contained on site.

Potential Environmental Impacts:

Environmental impacts are limited to surface soils given the frozen ground conditions.

Action Taken or Planned:

SM Fencing as dispatched to clean up release. Impacted soils have been excavated and taken to a disposal facility. Cleanup operations have been completed.

Wastes Disposal Location: Renewable Resources

Agencies Involved:**Updates**

Date: 12/9/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a truck overflow, remained on location according to the report. NDIC retains oversight.